CCR No. 96-1152	Logged Da	ate 10/03/96	Rev. Request Type				
Priority Routine	X Urgent	Emergency	Affected Release	Change Class			
Title (description) Remaining Tasks to Complete EDF Reconfiguration							
Documents Affected			Source Nos (RID, NCR, etc.) or Tech				
None		Referen	Reference				
RTM Change Start New Baseline							
Problem The EDF and Demo Room were reconfigured in 1996 to accommodate more hardware and present a better image of the overall operation. Several tasks remain to fully accomplish these goals.							
Proposed Solution							
 Dress wires and install cable covering on all Wright-Line racks. Install RAID for MSS4/CSS3 and MSS5/CSS4 into Comm Rack provided with EDF DAAC racks. Remove remaining shells 							
(cabinets) to storage.3. Provide EDF Planning with results of terminal server vs monitor switching evaluation for subsequent review and implementation.							
·							
Impact Analysis: Organizations Affected: BOO Contracts ESO FOS M&O							
QA R	el. A X Rel. B	Rel. IR1	MRS	SMO Subconts			
	Other						
Cost:	None X	Small (Not exceeding		Large			
Schedule:	None X	Other					
Additional LOC			Man-Month	s			
Materials							
Originator Jacob Eisenstein Signature Date							
Office	Office Manager	Olgriature		Date			
Office	Office Manager _	Signature		Date			
Disposition	Approved	Approved w/Comm	ent Forw	ard Disapproved			
Comments:							
(CCB Chairperson	Signature					

CM01JU95 ECS